



**LABOR RELATIONS DIVISION**

401 Broadway NE  
Albuquerque, NM 87102  
Phone: 505-841-4400  
Fax: 505-841-4424

226 South Alameda Blvd  
Las Cruces, NM 88005  
Phone: 575-524-6195  
Fax: 575-524-6194

[WWW.DWS.STATE.NM.US](http://WWW.DWS.STATE.NM.US)

**Wage Decision Approval Summary**

1) Project Title: CCC roof hail damage 2024-2787 BH  
Requested Date: 04/01/2024  
Approved Date: 04/02/2024  
Approved Wage Decision Number: CU-24-1162-B

**Wage Decision Expiration Date for Bids: 07/31/2024**

2) Physical Location of Jobsite for Project:  
Job Site Address: 417 Schepps Blvd.  
Job Site City: Clovis  
Job Site County: Curry

3) Contracting Agency Name (Department or Bureau): Clovis Community College  
Contracting Agency Contact's Name: Norman Kia  
Contracting Agency Contact's Phone: (575) 769-4074 Ext.

4) Estimated Contract Award Date: 03/20/2024

5) Estimated total project cost: \$1,113,344.63  
a. Are any federal funds involved?: No  
b. Does this project involve a building?: Yes - Clovis Community College  
c. Is this part of a larger plan for construction on or appurtenant to the property that is subject to this project?: No  
d. Are there any other Public Works Wage Decisions related to this project?: No  
e. What is the ultimate purpose or functional use of the construction once it is completed?: Prime base with elastomeric roof coating. Coat with finish coat of elastomeric roof coating. Remove and replace all coping that goes with elastomeric roof coating. Remove and replace all counter flashing that goes with elastomeric roof coating. Remove and replace 49 skylights. Remove and reset 10 skylights replacing the gaskets.

6) Classifications of Construction:

Classification Type and Cost Total	Description
<b>General Building (B)</b> <b>Cost: \$1,113,344.63</b>	Prime base with elastomeric roof coating. Coat with finish coat of elastomeric roof coating. Remove and replace all coping that goes with elastomeric roof coating. Remove and replace all counter flashing that goes with elastomeric roof coating. Remove and replace 49 skylights. Remove and reset 10 skylights replacing the gaskets.